

## BLADE REPAIR CAPABILITIES

### 3G6210A00131 / 4G6210A00132 MAIN ROTOR BLADE

- Anti-fretting Plates Replacement
- 4G FIPS Cable Testing and Replacement
- Leading Edge Closure Cover Replacement
- Leading Edge Fairing Replacement
- Lightning Conductor Strip Rebonding
- Lightning Conductor Strip Repair / Replacement
- Main Bushing Replacement
- Major Skin Repair
- Poly Root Boot Installation
- Refinish and Balance
- Root Closure Replacement(s)
- Skin Panels and Fairings Repair
- Skin Voids Repair
- Tip Cap Replacement(s)
- Trailing Edge Fairing Replacement
- Trim Tab Replacement(s)
- Wire Mesh Repair and Replace

### 3G6410A00133 / 4G6410A00133 TAIL ROTOR BLADE

- Pitch Control Arm Replacement
- Skin Repairs
- Refinish and Balance
- Reinforcement Shield Installation TMI139-415
- Root Repairs
- 4G FIPS Cable Replacement



For additional information, contact us or visit [www.bh.com/blade-repair](http://www.bh.com/blade-repair)

## CONTACT YOUR LOCAL BELL HELICOPTER BLADE FACILITY TO SCHEDULE BLADE REPAIR(S)

### BELL HELICOPTER

580-A St. Etienne Road  
Broussard, LA 70518  
United States  
Phone: 337.839.2119  
Email: [bladerepair@bh.com](mailto:bladerepair@bh.com)  
Repair Station: R8DR713Y

### RBI HAWKER LTD.

LIU FZS1 BD06/07  
JAFZ South, Dubai UAE  
PO Box 16784 Dubai  
Phone: +971.4.886.0144  
Email: [info@rbihawker.com](mailto:info@rbihawker.com)  
Repair Station: 6RBY351C (FAA), 145.0314 (EASA)

[BELLHELICOPTER.COM](http://BELLHELICOPTER.COM)



© 2017 Bell Helicopter Textron Inc. All registered trademarks are the property of their respective owners. The information herein is general in nature and may vary with conditions. Individuals using this information must exercise their independent judgment in evaluating product selection and determining product appropriateness for their particular purpose and requirements. For performance data and operating limitations for any specific mission, reference must be made to the approved flight manual. Bell Helicopter Textron Inc. makes no representations or warranties, either expressed or implied, including without limitation any warranties of merchantability or fitness for a particular purpose with respect to the information set forth herein or the product(s) and service(s) to which the information refers. Accordingly, Bell Helicopter Textron Inc. will not be responsible for damages (of any kind or nature, including incidental, direct, indirect, or consequential damages) resulting from the use of or reliance on this information. Bell Helicopter Textron Inc. reserves the right to change product designs and specifications without notice. BLADE REPAIRS AW139 170227-R02 EN