

BLADE REPAIR CAPABILITIES

212-015-501-XXX BELL 212 MAIN ROTOR BLADE

210-015-001-XXX BELL 210 MAIN ROTOR BLADE

- | | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <ul style="list-style-type: none"> • Abrasion Strip Replacement • Drag Bushing Replacement • Drag Plate Shimming Repair for Corrosion • Full Chord Skin Patch • Main Bushing Replacement | <ul style="list-style-type: none"> • Major Skin Repair • Oversize Main Bushing Replacement • Refinish and Balance • Root Cap Replacement • Root Closure Replacement • Splice Cover Replacement | <ul style="list-style-type: none"> • Supplemental Abrasion Strip Install • Tip Cap Replacement (Tie Down) • Tip Closure Replacement • Trailing Edge Extension Adjustment • Trailing Edge Extension Repair • Trim Tab Replacement |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

212-010-750-XXX BELL 212 TAIL ROTOR BLADE

210-010-001-XXX BELL 210 TAIL ROTOR BLADE

412-016-100-XXX BELL 412EPI TAIL ROTOR BLADE

- | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|
| <ul style="list-style-type: none"> • Fretting Pad Replacement • Refinish and Balance • Retention Bushing Replacement | <ul style="list-style-type: none"> • Skin Repairs • Supplemental Abrasion Strip Install | <ul style="list-style-type: none"> • Tip Block Replacement • Tip Closure Replacement |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|



For additional information, contact us or visit www.bh.com/blade-repair

CONTACT YOUR LOCAL BELL HELICOPTER BLADE FACILITY TO SCHEDULE BLADE REPAIR(S)

BELL HELICOPTER

580-A St. Etienne Road
 Broussard, LA 70518
 United States
 Phone: 337.839.2119
 Email: bladerepair@bh.com
 Repair Station: R8DR713Y

ROTOR BLADES LIMITED

Unit 5 B, Crusader Park
 Warminster, Wiltshire BA12 8BT
 United Kingdom
 Phone: +44.1985.847040
 Email: repairs@rotor-blades.com
 Repair Station: UK.145.01122

RBI HAWKER LTD.

LIU FZS1 BD06/07
 JAFZ South, Dubai UAE
 P.O. Box 16784 Dubai
 Phone: +971.4.886.0144
 Fax: +971.4.886.0145
 Email: info@rbihawker.com
 Repair Station: 6RBY351C (FAA),
 145.0314 (EASA)

BELLHELICOPTER.COM



© 2017 Bell Helicopter Textron Inc. All registered trademarks are the property of their respective owners. The information herein is general in nature and may vary with conditions. Individuals using this information must exercise their independent judgment in evaluating product selection and determining product appropriateness for their particular purpose and requirements. For performance data and operating limitations for any specific mission, reference must be made to the approved flight manual. Bell Helicopter Textron Inc. makes no representations or warranties, either expressed or implied, including without limitation any warranties of merchantability or fitness for a particular purpose with respect to the information set forth herein or the product(s) and service(s) to which the information refers. Accordingly, Bell Helicopter Textron Inc. will not be responsible for damages (of any kind or nature, including incidental, direct, indirect, or consequential damages) resulting from the use of or reliance on this information. Bell Helicopter Textron Inc. reserves the right to change product designs and specifications without notice. BLADE REPAIRS 214 170403-R03 EN