

BLADE REPAIR CAPABILITIES

222-015-500-XXX BELL 222B MAIN ROTOR BLADE

222-015-600-XXX BELL 222U / 230 MAIN ROTOR BLADE

- Abrasion Strip Replacement
- Abrasion Strip Splice Repair
- Doubler Debonding
- Main Bushing Replacement
- Major Skin Repair
- Refinish and Balance
- Spar Doubler Replacement
- Splice Cover Replacement
- Supplemental Tip Shoe Cover Install
- Tip Shoe Replacement
- Trailing Edge Doubler Replacement
- Trim Tab Replacement

222-016-001-XXX BELL 222 TAIL ROTOR BLADE

- Bearing and Sleeve Replacement
- Refinish and Balance
- Root Closure Replacement
- Skin Repairs
- Supplemental Abrasion Strip Install
- Tip Block Replacement
- Tip Closure Replacement



For additional information, contact us or visit www.bh.com/blade-repair

CONTACT YOUR LOCAL BELL HELICOPTER BLADE FACILITY TO SCHEDULE BLADE REPAIR(S)

BELL HELICOPTER

580-A St. Etienne Road
 Broussard, LA 70518
 United States
 Phone: 337.839.2119
 Email: bladerrepair@bh.com
 Repair Station: R8DR713Y

ROTOR BLADES LIMITED

Unit 5 B, Crusader Park
 Warminster, Wiltshire BA12 8BT
 United Kingdom
 Phone: +44.1985.847040
 Email: repairs@rotor-blades.com
 Repair Station: UK.145.01122

RBI HAWKER LTD.

LIU FZS1 BD06/07
 JAFZ South, Dubai UAE
 P.O. Box 16784 Dubai
 Phone: +971.4.886.0144
 Fax: +971.4.886.0145
 Email: info@rbihawker.com
 Repair Station: 6RBY351C (FAA),
 145.0314 (EASA)

BELLHELICOPTER.COM



© 2017 Bell Helicopter Textron Inc. All registered trademarks are the property of their respective owners. The information herein is general in nature and may vary with conditions. Individuals using this information must exercise their independent judgment in evaluating product selection and determining product appropriateness for their particular purpose and requirements. For performance data and operating limitations for any specific mission, reference must be made to the approved flight manual. Bell Helicopter Textron Inc. makes no representations or warranties, either expressed or implied, including without limitation any warranties of merchantability or fitness for a particular purpose with respect to the information set forth herein or the product(s) and service(s) to which the information refers. Accordingly, Bell Helicopter Textron Inc. will not be responsible for damages (of any kind or nature, including incidental, direct, indirect, or consequential damages) resulting from the use of or reliance on this information. Bell Helicopter Textron Inc. reserves the right to change product designs and specifications without notice. BLADE REPAIRS 222 170403-R01 EN