

BLADE REPAIR CAPABILITIES

206-015-001-XXX BELL 206L MAIN ROTOR BLADE

206-010-200-XXX BELL 206B MAIN ROTOR BLADE

206-011-250-XXX BELL OH-58 A/C

- Doublers Rebond
 - Flight Performance Wedging
 - Full Chord Skin Patch
 - Grip Pad Replacement
 - Grip Plate Remove, Reprocess, Rebond
 - Main Bushing Replacement
- Major Skin Repair
 - Refinish and Balance
 - Root Closure Replacement
 - Supplemental Abrasion Strip Install
 - Tell Tale Weight Inspection, Removal
 - Tip Cap Replacement
- Tip Cap Replacement (Tie Down)
 - Tip Closure Replacement
 - Tip Skin Repair
 - Trailing Edge Spar Repair
 - Trim Tab Replacement
 - Wear Pad Replacement

20631000-101 206B VAN HORN AVIATION MAIN ROTOR BLADE

- Grip Pad Replacement*
 - Grip Plate Assembly Replacement*
 - Grip Plate Bolts Replacement*
- Grip Plate Bushing Replacement*
 - Main Bushing Replacement*
 - Refinish and Balance*
- Wear Pad Replacement*
*Coming Soon

206-016-201-XXX BELL 206 SERIES TAIL ROTOR BLADE

- Bearing and Sleeve Replacement
 - Doubler Rebond
- Refinish and Balance
 - Skin Repairs
- Supplemental Abrasion Strip Install

2062200-301 206B AND 206L VAN HORN AVIATION TAIL ROTOR BLADE

- Abrasion Strip Replacement
 - Data Plate Replacement
 - Refinish and Balance
- Spherical Bearings Replacement
 - Wire Mesh Repair



For additional information, contact us or visit www.bh.com/blade-repair

CONTACT YOUR LOCAL BELL HELICOPTER BLADE FACILITY TO SCHEDULE BLADE REPAIR(S)

BELL HELICOPTER

580-A St. Etienne Road
Broussard, LA 70518
United States
Phone: 337.839.2119
Email: bladerrepair@bh.com
Repair Station: R8DR713Y

ROTOR BLADES LIMITED

Unit 5 B, Crusader Park
Warminster, Wiltshire BA12 8BT
United Kingdom
Phone: +44.1985.847040
Email: repairs@rotor-blades.com
Repair Station: UK.145.01122

RBI HAWKER LTD.

LIU FZS1 BD06/07
JAFZ South, Dubai UAE
P.O. Box 16784 Dubai
Phone: +971.4.886.0144
Fax: +971.4.886.0145
Email: info@rbihawker.com
Repair Station: 6RBY351C (FAA),
145.0314 (EASA)

BELLHELICOPTER.COM |

© 2017 Bell Helicopter Textron Inc. All registered trademarks are the property of their respective owners. The information herein is general in nature and may vary with conditions. Individuals using this information must exercise their independent judgment in evaluating product selection and determining product appropriateness for their particular purpose and requirements. For performance data and operating limitations for any specific mission, reference must be made to the approved flight manual. Bell Helicopter Textron Inc. makes no representations or warranties, either expressed or implied, including without limitation any warranties of merchantability or fitness for a particular purpose with respect to the information set forth herein or the product(s) and service(s) to which the information refers. Accordingly, Bell Helicopter Textron Inc. will not be responsible for damages (of any kind or nature, including incidental, direct, indirect, or consequential damages) resulting from the use of or reliance on this information. Bell Helicopter Textron Inc. reserves the right to change product designs and specifications without notice. BLADE REPAIRS 206 SERIES 170403-R04 EN